



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program May 28, 2013

Reviewed: 

Mine Name: Torrey Buff South	Permit Number: S/055/0022
Operator Name: Quality Building Stone	Inspection Date: May 22, 2013
Inspector(s): Wayne Western	Time:
Other Participants: none	Mine Status: ACT
Weather Condition: 70's clear skies	Last Inspection: April 21, 2011
Bond Renewal Date: 01/12/2009	Bond Amount: \$14,000.00
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: 2011	Acreage: 4 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

Permit fees were not paid in 2013. The Permittee should be reminded to pay permit fees.

Bond was set for renewal on January 12, 2009.

The site was stable.

The site was inactive during the inspection.


Conclusions and Recommendations:

The Division should continue to monitor the site.

The Division should follow up on the bond and permit fees.

Directions to Site:

Inspector's Signature




WHW:

cc: (OPERATOR)

John Reay, Hanksville BLM

Sue Fivecoat, Hanksville BLM

O:\M055-Wayne\S0550022-HansenTorreyBuff\inspections\Insp-05222013.doc



Equipment on site



Photo from on top



Working face



Working face